






3 MOST CRITICAL BLOWING MISTAKES



IMPROPER MICRODUCT-TO-CABLE RATIO



IMPROPER CABLE STORAGE AND HANDLING



FAILURE TO PREPARE THE MICRO-DUCT ROUTE

